

## Message Text

UNCLASSIFIED

PAGE 01 SEOUL 07996 080843Z  
ACTION SY-05

INFO OCT-01 EA-12 ISO-00 OC-06 CCO-00 FBOE-00 A-01

/025 W

-----011152 090934Z /20

R 080733Z SEP 78  
FM AMEMBASSY SEOUL  
TO AMEMBASSY MANILA  
INFO SECSTATE WASHDC 3366  
AMEMBASSY TOKYO  
AMCONSUL HONG KONG

UNCLAS SEOUL 7996

E.O. 11652: N/A  
TAGS: ASEC  
SUBJECT: CCC PROBLEM

REF: A. MANILA 14734, B. SEOUL 7250 (NOTAL)

1. SINCE REF (A) RECEIVED, TCU HAS RESOLVED PROBLEM DESCRIBED REF (B). METAL DRIP PAN HAS BEEN FABRICATED LOCALLY TO REPLACE BROKEN PLASTIC PAN, DRAIN PIPES HAVE BEEN DISMANTLED AND CLEANED THOROUGHLY AND DRAIN SYSTEM HAS BEEN REASSEMBLED THUS RESULTING IN ELIMINATION OF AIR FROM DRAIN PIPES. SYSTEM IS NOW DRAINING PROPERLY.
2. IT HAS BEEN ESTABLISHED THAT THE PROBLEM WAS ORIGINALLY CAUSED BY A BUILDUP OF GUNK IN THE DRAIN SYSTEM. THIS PROBLEM PRECLUDED THE DISSIPATION OF AIR FROM THE SYSTEM.  
GLEYSTEEN

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptoning:** X  
**Capture Date:** 01 jan 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 08 sep 1978  
**Decaption Date:** 01 jan 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 jan 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1978SEOUL07996  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Expiration:**  
**Film Number:** D780367-0833  
**Format:** TEL  
**From:** SEOUL  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1978/newtext/t19780988/aaaacune.tel  
**Line Count:** 42  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Message ID:** 25341054-c288-dd11-92da-001cc4696bcc  
**Office:** ACTION SY  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** 78 MANILA 14734, 78 SEOUL 7250  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 12 may 2005  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 1502195  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** CCC PROBLEM  
**TAGS:** ASEC  
**To:** MANILA  
**Type:** TE  
**vdkvgwkey:** odbc://SAS/SAS.dbo.SAS\_Docs/25341054-c288-dd11-92da-001cc4696bcc  
**Review Markings:**  
Sheryl P. Walter  
Declassified/Released  
US Department of State  
EO Systematic Review  
20 Mar 2014  
**Markings:** Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014